



## Spyder 2022 Horn Not Installed Properly - 140102

[Printable Version](#)

Rate This Article

(Average Rating: No Rating)

Version 1

Language

English ▼

[Show Properties](#)


### Article Detail

#### Problem:

The horn arm has been installed on the other side of the bracket so it is not positioned between the 2 stoppers, which causes a loose horn that can come into contact with the tie rod.

#### Solution:

Install the horn bracket between the 2 stoppers pointed with the red arrows



#### Inspection Procedure:

Check for proper bracket installation as shown in the above picture.

#### Warranty:

Normal PDI claim

---

**First Published By:** Eric Fauteux on 05/31/2022

**Last Modified By:** Eric Fauteux on 05/31/2022