



WARRANTY ENHANCEMENT PROGRAM (WEP)

USE ONLY IF FAILURE IS PRESENT

CONVENTIONAL AFTER TURBO CATALYST
(ATC) – AAPA0

BULLETIN NO: WP-22-010
DATE: 5-4-2022
REF: QA-220408-N1

SUBJECT VEHICLES: Certain 15MY-21MY Conventional Trucks equipped with a J08 engine.

OVERVIEW:

The ATC (After Turbo Catalyst) sensor of your vehicle may cause the MIL (Malfunction Indicator Light) to illuminate and output power restriction.

If this condition is found, refer to the appropriate Vehicle Identification Number in the warranty system to determine vehicle eligibility.

Warranty Terms

Perform this repair ONLY if failure condition is present.

-Warranty enhancement program: 10 years with no mileage limitation from the delivery date to the initial end purchaser, or five (5) years from the date of the customer notification letter, whichever is longer, will be covered by this program.

For any other failure modes, standard warranty conditions will be applied.



PARTS:

Model Year	Part Number	Part Description	Quantity
15-16	17401-E0P30	Exhaust Pipe Sub-Assembly	1
17-21	17401-E1550	Exhaust Pipe Sub-Assembly	1
15-21	S2410-91830	Gasket Sub-Assembly	2
15-21	17451-E0100	Exhaust Pipe Gasket	1
15-21	S1710-41580	Gasket Sub Assembly, Exhaust Manifold	1

BEFORE YOU BEGIN:

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **WARNINGS** and **NOTICES** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a flat, level and solid surface.
- Place the gear shift lever in "Neutral" or "Park".
- Apply the parking brake firmly and confirm parking brake activation.
- Turn off the engine and remove the key from the ignition switch.
- Always wear safety glasses or goggles to protect your eyes.
- Place wheel chocks in front of and behind all the wheels to prevent the vehicle from moving.

REPAIR PROCEDURE:

Please refer to the appropriate Hino Service Manual for replacement instruction.



CLAIM APPLICATION

Reimbursable in accordance within the terms and policies of the Hino limited warranties.

Conventional After Turbo Catalyst Replacement:

- a) Campaign No: AAPA0
- b) Labor charge: 2.9 hours
- c) Warranty code: 11316
- d) Trouble code: 98
- e) Operation code: 11301CRE
- f) Original failed part: 9999999999

