

Service Bulletin


Bulletin No.: 22-NA-117

Date: June, 2022

INFORMATION

Subject: Information on Driver Side Outside Rearview Mirror (OSRVM) Image Distortion, Mirror Glass Appears Distorted, Blurry or Wavy

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Engine.	ITAIISIIIISSIOII.
Chevrolet	Spark	2021	2022	_	_	All	All



Copyright 2022 General Motors LLC. All Rights Reserved.



6083507

Some customers may comment that the mirror glass appears to be distorted, blurry, or wavy.

Cause

The cause of the condition may be that when viewed in full sunlight, the mirror appears to be blurry or wavy. The distortion is actually a reflection of the left side I/P vent onto the driver's side glass, as reflected in the mirror.



Correction

6083508

View the mirror in daylight with the window up (1) and then down (2). If the distortion is due to the reflection, then no repair is necessary. Otherwise, verify mirror is fully seated prior to replacement.

Please communicate to the customer that the OSRVM system is functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.

Version	1			
Modified	Released May 31, 2022			

