



## Mack Chassis Model LEU613 " Cab Right Hand Drive Only " And " Allison Transmission Only " Low Air Alarm & Turn Signal Alarm " Not Operating After The Cab Harness Is Replaced



> Internal Content

Please be aware if you have replaced the Cab Harness on a Mack Chassis LEU613 " Right Hand Drive Only" with an " Allison Transmission Only " and there is no " Low Air Alarm & Turn Signal Alarm " check and confirm that circuit wire number CB13A is removed from the Gauge Driver Module ( GDM ) connector.



Tags

[mack](#)

[right hand drive](#)

[k92184448](#)

### Related links and attachments

No links or attachments available



### Feedback

[Give feedback](#)

to help improve the content of this article