

SSM 50823 - 2021-2022 F-Super Duty/Navigator/Expedition - Roof Opening Panel/Sunshade Initialization Failure

Some 2021–2022 F–Super Duty, Navigator, and Expedition vehicles equipped with a power roof opening panel may experience a malfunction or an inoperable condition with the power roof opening panel or sunshade where the initialization procedure may need to be performed. The Workshop Manual (WSM), Section 501–17 > General Procedures > Power Roof Opening Panel Initialization is the process of being updated. At this time, when directed in Step 1 to switch the ignition ON, the engine should then be started and allowed to run. When Step 2 is reached and the vehicle is turned back on, the engine should be restarted and allowed to run through completion of the initialization procedure.

APPLICABLE VEHICLES

2021 - 2022 TRUCK: B8 U553N EXPEDITION

2021 - 2022 TRUCK: FE P558N SUPER DUTY

2021 - 2022 TRUCK: B9 U554N NAVIGATOR