



David J. Johnson
 Director
 Service Engineering Operations
 Ford Customer Service Division

Ford Motor Company
 P. O. Box 1904
 Dearborn, Michigan 48121

June 2, 2022

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE RECOMMENDED DEMONSTRATION / DELIVERY HOLD -
 Update Prior to Sale 22U08 Advance Notice**
 Certain 2022 Model Year 3.5L GTDI Equipped Expedition, F-150 and Navigator
 Vehicles
 Heavy Grey/Blue Smoke and/or Oil from Exhaust Tailpipe(s)

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Expedition	2022	Kentucky Truck	April 29, 2022 through May 18, 2022
F-150		Dearborn Truck	April 20, 2022 through May 24, 2022
		Kansas City	April 28, 2022 through May 12, 2022
Navigator		Kentucky Truck	April 21, 2022 through May 3, 2022

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS PROGRAM

In some of the affected vehicles, it's possible the left-hand turbo oil drain hole was incompletely drilled during the engine block machining process. A vehicle built with an engine block that has an incomplete turbo oil drain hole may experience heavy gray/blue smoke with oil from the exhaust tailpipe(s), which could lead to a malfunction indicator light on the instrument panel cluster.

SERVICE ACTION

Ford Motor Company recommends dealers not demonstrate or deliver any new in-stock vehicles involved in this customer satisfaction program until after the inspection/repair is performed. A complete Dealer Bulletin will be provided to dealers by the week of June 13, 2022 when it is anticipated that parts ordering information and repair instructions will be available to support this program.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a program.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

David J. Johnson