

Subject: Engineering Information - Service 4WD Message Illuminated On the Driver Information Center (DIC) and/or Grinding, Scraping and/or Squeal Type Noise Heard From the Rear of the Vehicle

This PI has been revised to end the need for information from the field. Please discard PIE0659.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2020	2022	-	-	Equipped with 3.0L, 5.3L, 6.2L Engines (RPOs LM2, L82, L84, L87, LZ0)	Equipped with 6 SPD, 8 SPD Transmissions (RPOs MYC, MQE, MQC, MHO)
Chevrolet	Silverado 1500	2020	2021			Equipped with 2.7L, 3.0L, 5.3L, 6.2L Engines (RPOs L3B, LM2, L82, L84, L87, LZ0)	
	Silverado 1500 New Model) - 2WD	2022	2022				
	Silverado 1500 New Model) - 4WD						
	Suburban	2020					
	Tahoe						
GMC	Sierra 1500	2020	2021			Equipped with 6 SPD, 8 SPD Transmissions (RPOs MYC, MQE, MQC, MHO)	
	Sierra 1500 New Model) - 2WD	2022	2022				
	Sierra 1500 New Model) - 4WD						
	Yukon Models	2020					Equipped with 6 SPD Transmission (RPO MYC)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 05, 2021 Revised January 12, 2022 – Ended the need for further information from the field.