



Preliminary Information

PIT5920 Buzz Rattle or Tick Noise From Right Fender Area

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2020 - 2022	All	All	All	All
GMC	Canyon	2020 - 2022	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	None
Condition:	Buzz, rattle or tick noise from right fender area.
Cause:	Fender support not secured to the fender.

Correction:

Inspect the support shown below if it can be moved back and forth secure it to the fender with panel bonding adhesive and allow to set.



Version History

Version	1.0
Modified	Created 05/23/2022



© 2022 General Motors. All Rights Reserved.