

Technical Journal

TITLE:

Center wheel caps, removal instructionREF NO:
TJ 28739.3.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2022-04-29STATUS DATE:
2022-05-06FUNC GROUP:
7718FUNC DESC:
Hub cap**Page 1 of 7**

“Right first time in Time”

Attachment

File Name	File Size
TJI-471202-1_1_2_en-US. (2).pdf	0.3110 MB
TJ_28739.jpg	0.794 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* added picture, vehicle type, updated the description.

When replacing a tyre or when the wheel must be balanced it is required to first remove the complete wheel and then the center wheel cap from the wheel.

If the center wheel cap is removed incorrectly, for instance using a smallscrew driver to remove the center wheel cap from the front side, **Note:** Doing this will cause damage to the rim.

The correct way to remove the center wheel cap is to push it out from the inner side, refer to the attached TJ instruction.

Technical Journal 28739.3.0

CSC Customer Symptom Codes

Code	Description
4K	General/Corrosion (not perforation)
1C	Service/repair/Administrative and Factory scheduled maintenance
V1	Tires/Vibratin/out of round

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
1XX							2007-9999		0000001-9999999	200605-999952
2XX							2016-9999		0000001-9999999	201505-999952
5XX							2013-9999		0000001-9999999	201220-999952

SERVICE:

When the center wheel cap needs to be removed from the rim, follow the attached TJ instruction.

Warranty claim info:

This TJ is for information only and the service described is not covered by warranty. Any damage caused by not following the advice will not be covered by warranty either.

VEHICLE REPORT:

No.

To view TJ attachments continue to next page. This TJ has two attachments.





Volvo Car Customer Service

TJ Instruction VCC-471202-1

Title	Wheel cap	Page	1 (4)
Action	Removal	Operation number:	98522-2

Issue	Date	Reason
1	2014-01	First issue

Affected vehicles



Model year	Model
2007- present	All

Materials

Materials	Qty.	Part No.	Notes
Installation paste	1.0	1161397	

Removal


Note! Removal steps in this procedure may contain installation details.



Warning! Make sure that the mating faces are clean and free of corrosion and foreign material.

Use: Installation paste , 1161397

Check that the screws are tightened to the specified torque.



Installation

To install, reverse the removal procedure.