

SSM 50834 - 2022 F-150 Lightning - Without Remote Park Assist - Frunk Exterior Buttons Inhibited During Two Stage Lock

Some 2022 F-150 Lightning vehicles not equipped with the remote park assist may experience an inoperative power frunk when using the exterior frunk button. Vehicles not equipped with the remote park assist feature will not have the front antennas for a passive key fob search. To open and/or close the frunk from only the exterior button on vehicles without remote park assist, the vehicle must be 2-stage unlocked. The frunk can also be opened by first pressing the instrument panel or SYNC screen button then using the exterior frunk button when the vehicle is single-stage or 2-stage unlocked. The key fob frunk button can be used to open and/or close the frunk regardless of lock status. Engineering is currently investigating a software update to enhance power frunk operation. A software update is anticipated late Q4 2022. Continue to monitor OASIS for updates.

APPLICABLE VEHICLES
2022 TRUCK: FD P702N F150