

2022 Ascent

COMPLAINT: PORCH LIGHT NOT WORKING CORRECTLY.

CAUSE: LIGHT IS WIRED BACKWARDS.

CORRECTION: REMOVED LIGHT & FOUND HOT WIRE TO GROUND & GROUND TO HOT.

REPAIRED WIRING, REPLACED FUSE & TESTED GOOD.

TIME: .6 0.60 approved.

PART NEEDED: NONE