

Subject

Under Floor Wire Harness for Motor Generator - Connector Cover has Missing or Damaged Appearance

Market

USA

Service Category

Engine/Hybrid System

Section

Hybrid/Battery Control System

Applicability

Highlander HV/RAV4 HV/RAV4 Prime/Venza




APPLICABLE VEHICLES

2021-2022	Venza HV	2021-2022	Highlander HV
2021-2022	RAV4 Prime	2021-2022	RAV4 HV

CONDITION

On some 2021-2022MY Highlander HV, RAV4 HV, RAV4 Prime and Venza models, the connector cover for the Under Floor Wire Harness for the Rear Motor Generator may have the appearance of being damaged or missing. Please review the image below to see the connector cover condition.

*A	2WD Models	*B	AWD Models
*1	Compressor with Motor Assembly	*2	Power Cable (HV Air Conditioning Wire)
*3	Inverter with Converter Assembly	*4	Hybrid Vehicle Transaxle Assembly
*5	HV Battery	*6	Service Plug Grip
*7	Power Cable (HV Floor Under Wire)	*8	Rear Drive Unit (Rear Traction Motor with Transaxle Assembly)



Subject

Under Floor Wire Harness for Motor Generator - Connector Cover has Missing or Damaged Appearance

Market

USA

Applicability

RECOMMENDATIONS

This appearance is normal and is part of the connector cover design. No repairs are needed.

LINK REFERENCES

This Tech Tip does not contain any link references