

## **SSM 50855 - 2022 F-Super Duty - U0140 Stored In The TRM After A Software Update**

Some 2022 F-Super Duty vehicles equipped with a trailer brake controller and a 12.3 inch center display screen may exhibit diagnostic trouble code (DTC) U0140:82 stored in the trailer module (TRM) after completing a TRM software update. This may be due to software parameters in the TRM. To correct the condition, perform the TRM - Trailer Module (TRM) Configuration application using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool.

APPLICABLE VEHICLES  
2022 TRUCK: FE P558N SUPER DUTY