Subject:

Engineering Information - Service Engine Soon (SES) Lamp Illuminated, Service Emission System and/or DEF Level Low Message On Driver Information Center (DIC), DEF Level Sensor Reading Incorrectly, DEF Level Sensor Being Erratic, DEF Level Sensor Stuck and/or High DEF Consumption

This PI has been revised to end the need for information from the field. Please discard PIE0695.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2020	2021	_	_	Equipped with 3.0L	_
	Silverado 1500 LTD (RPO J21, VIN Digit 5 = W/Y)	2022	2022			(RPO LM2)	
	Silverado 2500HD/3500HD	2020				Equipped with 6.6L (RPO L5P)	
GMC	Sierra 1500	2020	2021			Equipped with 3.0L (RPO LM2)	
	Sierra 1500 Limited (RPO J21, VIN Digit 5 = 8/9)	2022	2022			(RPO LWZ)	
	Sierra 2500HD/3500HD	2020				Equipped with 6.6L (RPO L5P)	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released May 11, 2022 Revised June 08. 2022 – Ended the need for further information from the field.