

Subject: Engineering Information - Request for Pictures of Broken Wire in Harness Between ECM and Multifunction Sensor (MAF Sensor), DTCs U060F, U1346, P0101, P0102 and/or P1101 Set (U.S. ONLY)

This EI has been revised to end the need for information from the field. Please discard PIE0682.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020	2022	—	—	1.2L or 1.3L Engine (RPOs LIH, L3T)	—
Chevrolet	Trailblazer (VIN M)	2021					

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released March 09, 2022 June 15, 2022 – Ended the need for further information from the field.