

## Sliding sunroof panel of panoramic sliding sunroof reversed (temporarily, once, multiple times) during closing process with no obstruction

---

Topic number	LI77.21-P-074971
Version	1
Function group	77.21 - Panoramic roof
Date	6/16/22
Validity	Model series 206 with SA code 413 (Panoramic roof) Model series 297 with SA code 413 (Panoramic roof)
Reason for change	

---

### Complaint

Sliding sunroof panel of panoramic sliding sunroof reversed (temporarily, once, multiple times) during closing process without an obstruction (triggering of Pinch Protection).

### Cause

Under investigation.

Please open a PTSS/TIPS case for with a quick test and CU log of the Panoramic Roof TSSR223.

### Remedy

Do NOT perform a teach-in of the roof.

Please perform the following steps:

1. Create a PTSS/TIPS case
2. Create control unit log of panoramic roof control unit (TSSR223, A98, PSD) and attach to PTSS/TIPS case

Normalize panoramic roof with XENTRY and carry out the teach-in run for automatic reversing function.

WIS-References		
Document number	Title	Note
AD00.00-P-2000-06FR	Connect/disconnect diagnostic device	-

Symptoms
Body > Roof system > Tilting/sliding sunroof system > Does not close

Operation numbers/damage codes
--------------------------------

# XENTRY TIPS

---

Op. no.	Operation text	Time	Damage code	Note
541011	Perform control unit log incl. quick test	003 AW	7811DGR	For model series 297
776901	Standardize panoramic sliding sunroof and teach in automatic reversing function	ZM	8201DT9	For model series 206
776901	Standardize panoramic sliding sunroof and teach in automatic reversing function	ZM	7811DGR	For model series 297
541011	Perform control unit log incl. quick test	003 AW	8201DT9	For model series 206