

Subject:

REAR FENDER LINER (MUDGUARD) DOES NOT FIT CORRECTLY

Service Alert No.: SA-037/22

Last Issued : 06/03/2022

BULLETIN NOTES

APPLICABLE MODEL(S)

2023 CX-50

DESCRIPTION


Customers may complain about either rear fender liner (mudguard) hanging down because it is too short to fit into the fender trim.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE

1. Remove the tire.
2. Remove ALL fasteners from the fender liner.



3. Shift the liner upward and outward.
4. Hook the section of the liner that was hanging down into the space between the fender and fender garnish.



5. Reinstall and tighten all the fasteners while holding the fender liner in place.

Is the fender liner staying up?

YES: Continue to STEP 7.

NO: Go back to STEP 2.

6. Reinstall the tire.
7. Take the vehicle on a short test drive to confirm the liner stays in place.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.