

2020 TLX Rear Toe Actuator Warning Lights with C1600-94

AFFECTED VEHICLES

Year	Model	Trim Level
2020	TLX	ALL with FWD

Clients are experiencing multiple warning lights coming on with DTC C1600-94 *Precision All Wheel Steer System Unexpected Operation*. Do an all DTC check. If you can duplicate and related codes are present, follow the appropriate troubleshooting. If you cannot duplicate the contention after clearing the DTC, then follow up with the client and document the driving conditions needed to replicate the client's complaint.

To better understand the client's complaint at the time the warning lights came on, please do the following:

- 1: Provide photos of LH/RH Rear Toe Actuators Assy (See samples below.) and do an alignment (Provide before/after data)
- 2: Ask if the customer noticed the following:
 - Limp mode (Yes/No):
 - Road conditions (dry/wet/snow/gravel/grass):
 - Throttle input (accel/decel/cruising):
 - Driving conditions (straight ahead or obstacle avoidance maneuver e.g., pothole/ball/animal):
 - If turning, steering wheel input (e.g., 9 O'clock, 1 O'clock):

With the vehicle on a lift, take a picture from below the rear toe actuator and from above.



Below part view



Above part view

Please provide VIN, mileage and customer feedback to tis@ahm.honda.com.