

TECHNICAL TOPICS

BODY/CHASSIS



Powered Loadspace Cover Does Not Open Correctly	22 – 23MY New Range Rover (L460)
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A customer may report that the powered loadspace cover does not open properly when actuated. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- The loadspace cover may not initiate the fold properly due to incorrect hinge break point angle. <p><u>Status:</u></p> <ul style="list-style-type: none">- Engineering is currently investigating this concern.- SSM 75746 has been published to provide an interim solution to the concern.	

