

TECHNICAL TOPICS

BODY/CHASSIS



Approach Unlocking, Keyless Entry & Unlocking Inoperative	22MY New Range Rover (L460)
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">- A customer may report that the Approach Unlocking or Keyless Entry and unlocking is inoperative with the smart key. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">- The Remote Function Actuator (RFA) may not recognize the smart key properly. The vehicle can be unlocked using the emergency key blade and the engine can be started using the Immobilizer Antenna (IAU) by proper placement of the smart key. <p><u>Status:</u></p> <ul style="list-style-type: none">- Engineering is currently investigating this concern.- SSM 75742 has been published to provide a process to restore RFA operation.	<p>The diagram illustrates the correct orientation for the smart key. It consists of four numbered steps (1-4) showing the key being tilted from a horizontal position to a vertical position. Step 1 shows the key horizontal. Step 2 shows the key tilted upwards. Step 3 shows the key tilted further, with a black arrow pointing to the bottom edge of the key. Step 4 shows the key fully vertical, with a black arrow pointing to the bottom edge of the key. The diagram is enclosed in a rectangular frame with a small 'EX0214' label at the bottom left.</p>

