

**Subject:** Engineering Information - Malfunction Indicator Lamp (MIL) Illuminated, Service Rear Axle Message On Driver Information Center (DIC), Transmission Shifting Concerns

**Attention:** Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL. Refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

*This EI has been revised to add the 2023 Model Year and update the Correction. Please discard PIE0700.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2023	—	—	—	8 SPD Automatic (RPO M1L)

<b>Involved Region or Country</b>	North America
<b>Condition</b>	<p><b>Important:</b> If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.</p> <p>Some customers may comment on having one or more of the following conditions:</p> <ul style="list-style-type: none"> <li>Malfunction Indicator Lamp (MIL) illuminated</li> <li>Service Rear Axle message on driver information center (DIC)</li> <li>Transmission shifting concerns</li> </ul>
<b>Cause</b>	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

## Correction

If you encounter a vehicle with the above concern, contact one of the engineers listed below for steps going forward.

## Contact Information

The Contact Information has been redacted.

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

## Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
2888688*	Engineering Information - Malfunction Indicator Lamp (MIL) Illuminated, Service Rear Axle Message On (DIC)	0.5 hr

\*This is a unique Labor Operation for bulletin use only.

<b>Version</b>	2
<b>Modified</b>	Released May 13, 2022 June 23, 2022 – Added the 2023 Model Year and updated the Correction.