

Subject: Engineering Information – (for Pictures Only) – Front/Rear Side Door Mis-Alignment

This EI has been revised to end the need for information from the field. Please discard PIE0668.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EUV	2022	2022	—	—	—	—
	Bolt EV						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released November 02, 2021 Revised June 29, 2022 – Ended the need for further information from the field.