



Service Bulletin

Bulletin No.: 22-NA-035

Date: February, 2022

INFORMATION

Subject: Chrome Around the Far Right Dash Vent Does Not Illuminate like the Center Dash

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2021	2022	—	—	—	—

Involved Region or Country	United States, Canada, Mexico
Condition	<p style="text-align: right; font-size: small;">5989321</p> <p>Some customers may comment on the chrome around the far right dash vent (1) does not illuminate like the left dash (2) and center dash (3), as shown in the picture above.</p>
Cause	DO NOT replace any parts to correct the customer concern. This is the normal operation.
Correction	Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Version	1
Modified	Released February 15, 2022

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**