

Technical Service Bulletin

91 DTC U101400 stored in the telematics control module

91 22 10 2057715/4 July 12, 2022. Supersedes Technical Service Bulletin Group 91 number 20-75 dated June 5, 2020, for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|--|-------------|-----------|----------------------------|
| A4 allroad, A4, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, and e-tron quattro | 2019 | All | Not applicable |
| A6, A7, A8, Q5, SQ5, Q7, and Q8 | 2019 – 2020 | | |
| A6 allroad, S6, S7, A8 e quattro, S8, e-tron Sportback quattro, Q5 e quattro, SQ7, SQ8, and RS Q8 | 2020 | | |

Condition

Page 1 of 3



Technical Service Bulletin

| REVISION HISTORY | | | |
|------------------|------------|---|--|
| Revision | Date | Purpose | |
| 4 | - | Revised Condition (removed customer states section) | |
| 3 | 06/05/2020 | Revised header (Added A8) | |
| 2 | 04/28/2020 | Revised header (Added Audi e-tron quattro and Q7) | |

Workshop findings:

The following DTC may be stored in the telematics control module, J949 (address word 0075):

• DTC U101400 (Control module incorrectly coded).

Technical Background

A timing issue on start-up can cause the telematics control module to erroneously enter this DTC.

Production Solution

Not applicable.

Service

No repair is available at this time.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. This DTC does not have any impact on functionality or customer experience.

Page 2 of 3

© 2022 Audi of America, Inc.



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2057715) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.