

SSM 50917 - 2022 Maverick - Integrated Trailer Brake Setting Menu Is Not Displayed In The IPC

Some 2022 Maverick vehicles built on 3-Jun-2021 and through 25-Nov-2021 may exhibit a condition where the integrated trailer brake setting menu is not displayed in the instrumental panel cluster (IPC). This may be due to a misconfigured IPC. To correct this condition, run the IPC-Configuration app using Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 10849 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2022 CAR: FE P758N C-PICKUP