

SERVICE BULLETIN 595 - SPEED TRIPLE 1200 RR INSTRUMENT COWL



Notice Information

Ref	21412
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (USCA) – May 2, 2022

TOL Ref. #21412 - SVC

SERVICE BULLETIN 595 – Speed Triple 1200 RR Instrument Cowl

Dealers are requested to replace instrument cowls on below Speed Triple 1200 RR models following the attached instructions.

The complete Service Bulletin 595 and instructions can be found attached and at the TriumphOnline.net (TOL) [Service Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action.

Replace Instrument Cowl				
Bulletin Number	Models Affected	VIN Range		Markets Affected
595	Speed Triple 1200 RR	From AV0486	To AZ5696	All Markets

Reminder: use the "VIN Enquiry" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

-

Identification of Affected Motorcycles

Speed Triple 1200 RR motorcycles in the above VIN range.

-

Notes:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

-

Warranty Claim Instructions

Bulletin Number	Fault Code	Repair Code	Description	Repair Time Allowance
595	020130995	99595	Replace instrument cowl	0.21 Hrs

-

Genuine Parts Information

Bulletin Number	Part Number	Description	Quantity
595	T2311485	Parts kit	1

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.