



Bulletin No.: PIC6435B
Published date: 06/6/2022

Preliminary Information

PIC6435B Service Adaptive Headlamp Message, Lin Bus DTC U1523 Setting After Right Headlamp Replaced

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	XTS	2013 - 2014	All	All	All	All

Involved Region or Country	North America
Condition	Service Adaptive Headlamp message with DTC U1523 setting after right headlamp replacement.
Cause	Part Issue

Correction:

A parts issue previously caused replacement right headlamps to set a U1523 when installed. Certified stock is now available.

Version History

Version	3
Modified	03/31/2021 - Created on. 05/07/2021 - Updated Model Years and Correction. 06/09/2021 - Update to inform certified stock is now available.



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.