

2021 Ascent

AC FAN IS HITTING SOMETHING AND BLACK FABRIC IS COMING OUT. A/C MOTOR MOUNT
LOOSE FOUND BOLT IN BOTTOM A/C TRAY REINSTALL BOLT ADD LOCK TITE TORQUE TO SPECK.
TESTED AND NO MORE NOISE, FUNCTIONING PROPERLY. Requesting .30 labor **0.30 approved.**