

ServiceNews Article

July 2022 B22070B Version 1

Driver's Side Door Weatherstrip is Distorted

AFFECTED VEHICLES

Year	Model	Trim Level
2023	Integra	ALL

We've received a few contacts regarding a distorted driver's side door weatherstrip, and we wanted to let you know there is nothing wrong with the part.

Now, rather than just leave you wondering why it's there, here's something interesting. The two nibs found on the weatherstrip was manufactured to channel the water away from the driver when the door is opened.

So, if a client comes in with this question, or a TQI Tech is curious about it you have the answer.

