

# SS 714-WST 2022 49X Primary Mirror Shaking and Vibration

## Applicable Vehicles

49X vehicles built with primary mirrors

## Symptoms

Mirror shaking and or vibrating

## Issue

Supplier tooling wear allowing reduced clamp load by the carrier lock ring

## Solution

Replace mirror parts per crossover list below:

DISCONTINUED:

-----

22-75514-503 THRU 05

A22-79064-000 THRU 15

REPLACED BY:

-----

22-78779-501 THRU 03

A22-78779-000 THRU 15

Labels :

49X

Add tags



2 Kudos

Comment

