

## **SSM 50965**

### **2022 Bronco - Intermittent Fast Turn Signal - Built On 13-Apr-2022 And Through 20-Apr-2022**

Some 2022 Bronco vehicles built on 13-Apr-2022 and through 20-Apr-2022 may exhibit an intermittent turn signal that blinks fast and diagnostics trouble codes (DTCs) B1497 and/or B1498 set within the body control module (BCM). To correct this condition, replace the appropriate left and/or right LED control module that corresponds with the DTCs set in the BCM. Refer to Workshop Manual, Section 417-01.