

<BULLETIN DRAFT>

No. Bulletin #01-

085

Model 520 HVAC Service Ports Spaced Incorrectly


Author: Darrell Cook

7/12/2022

Title (metadata)	Bulletin #01-085: Model 520 HVAC Service Ports Spaced Incorrectly
Description	Model 520 HVAC Service Ports Spaced Incorrectly
Bulletin No.	Bulletin #01-085
Bulletin Category	Field Service
Supplier (Recall Only)	
Image	
Service Subject	Model 520 HVAC Service Ports Spaced Incorrectly
Section	HVAC - 01
What's New Abstract	Info Only – Certain 520 model chassis built between 2014 and 2021, and equipped with the Red Dot HVAC system, may have service port spacing which will not allow the connection of a pressure gauge to both the high and low side service ports simultaneously. A specific tool is available from the supplier that will allow a technician to bypass this design issue.
Revision	
Condition / Chief Complaint	HVAC service ports are spaced too closely together and prevent a technician from connecting a pressure gauge to both high and low side service ports at the same time.
Chassis Affected	520 model chassis with Red Dot HVAC system.

Model 520 HVAC Service Ports Spaced Incorrectly

Bulletin #01-085

Service Action	<p>Information Only A tool is available for dealerships to purchase and use to bypass the current design.</p>									
Parts	<p>Parts are available from supplier "AirSept".</p> <table border="1" data-bbox="362 919 1193 1024"> <thead> <tr> <th>Quantity</th> <th>Part Number</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td>1*</td> <td>90003</td> <td>High Side Extender</td> </tr> <tr> <td>1*</td> <td>90033</td> <td>Low Side Extender</td> </tr> </tbody> </table> <p>*Purchase either the High or Low side extender part listed above as either one will work to bypass the current design.</p> 	Quantity	Part Number	Description	1*	90003	High Side Extender	1*	90033	Low Side Extender
Quantity	Part Number	Description								
1*	90003	High Side Extender								
1*	90033	Low Side Extender								
Background										
Procedure										

Model 520 HVAC Service Ports Spaced Incorrectly

Bulletin #01-085

Links	Add link to AirSept from web.
Channels	KWUS <input type="checkbox"/> KWCA <input type="checkbox"/> KWGS <input type="checkbox"/> PBUS <input checked="" type="checkbox"/> PBCA <input checked="" type="checkbox"/> Same bulletin published to KW & PB regions? No
Publish On	Click or tap to enter a date.