Complaint Of Noise From Area Of Steering Column

Topic number LI46.15-P-070510

Version 3

Function group 46.15 - Steering column adjustment

Date 7/11/22
Validity Model 177

model 247

model 118

model 167

Reason for change Model series 167 added

Complaint

Noises from the area of the steering column.

- Creaking
- Squeaking
- Chattering
- Humming
- Grinding

Cause

At present, there are no known noise problems with the steering column.

Remedy

Check surrounding area of the steering column for possible noises.

- Instrument panel support
- Steering column switch module

If the cause of the noise can be narrowed down to the steering column, create a PTSS case.

Attach a detailed description of the noise complaint, together with images and a recording of the noise.

A detailed description includes:

XENTRY TIPS

- Position of height and longitudinal adjustment when the noise occurs
- If possible, locate affected component part on steering column
- State any change in the noise when steering column component parts are touched (e.g. spring, etc.)

| Symptoms |
|--|
| Chassis/suspension > Steering system > Noises > Beeping |
| Chassis/suspension > Steering system > Noises > Dragging/squealing |
| Chassis/suspension > Steering system > Noises > Cracking |
| Chassis/suspension > Steering system > Noises > Hissing/streaming |
| Chassis/suspension > Steering system > Noises > Chattering/knocking |
| Chassis/suspension > Steering system > Noises > Humming/vibrations |
| Chassis/suspension > Steering system > Noises > Clattering |
| Chassis/suspension > Steering system > Steering column adjustment > Clattering |
| Chassis/suspension > Steering system > Steering column adjustment > Corrosion |
| Chassis/suspension > Steering system > Steering column adjustment > Knocks |
| |

| Operation numbers/damage codes | | | | | |
|--------------------------------|----------------|------|-------------|------|--|
| Op. no. | Operation text | Time | Damage code | Note | |