



Subject: SWITCH DECORATIVE TRIM IS PEELING	Service Alert No.: SA-049/22
	Last Issued : 07/27/2022

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2019 - 2021 MAZDA3

2020 - 2021 CX-30

DESCRIPTION

Some vehicles may exhibit the trim peeling off the EPB (Electronic Parking Brake) or power window switches.

REPAIR PROCEDURE

POWER WINDOW SWITCH

Was the vehicle produced before February 01, 2020?

YES - Replace the affected power window switch.

NO - This repair information does not apply. Confirm there was no outside influence and then diagnose and repair as required.

EPB SWITCH

Was the vehicle produced before November 01, 2020?

YES - Replace the EPB switch.

NO - This repair information does not apply. Confirm there was no outside influence and then diagnose and repair as required.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.