

CAMPAIGN LAUNCH STATUS



N691 UPS – CHANGE TO ENABLE SOFTWARE OVER THE AIR (SOTA)

UPDATE PRIOR TO SALE N691- CHANGE TO ENABLE SOTA – CCF UPDATE	
AFFECTED MODELS	23MY Discovery and Defender
VOLUME AFFECTED	1836 US 309 CAN
REPAIR	Certain vehicles have been identified that may have been manufactured with an incorrect specification Car Configuration File(CCF) preventing PIVI updates over the air. Retailers will perform a Car Configuration File(CCF) update to enable the feature.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	June 21st, 2022
Notes	All affected vehicles in retailer stock must have this repair completed prior to sale and delivery.

