





GROUP	MODEL
ELE	2022-2023MY Carnival (KA4)
NUMBER	DATE
263	August 2022

TECHNICAL SERVICE BULLETIN

SUBJECT: **LOW PITCH & HIGH PITCH HORN REPLACEMENT**

This bulletin provides information to replace both the low and high pitch horns on some 2022-2023MY Carnival (KA4) vehicles produced from January 4, 2021 through May 2, 2022, which may exhibit and inoperative low or high pitch horn. If either horn is inoperative, then follow the procedure outlined in this publication to replace BOTH low and high pitch horns.




Replacement Procedure:


1. Replace the both the low (A) and high (B) pitch horns by referring to "Body Electrical System → Horn → Removal and Installation" in the applicable Shop Manual on KGIS.

ⓘ IMPORTANT

Even if only one (1) of the horns is inoperative, replace both horns.



2. Confirm normal horn operation.



SUBJECT:

LOW AND HIGH PITCH HORN REPLACEMENT**AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Carnival (KA4)	January 4, 2021 to May 2, 2022

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
Low Pitch Horn Assy	96611 R0000		1
High Pitch Horn Assy	96621 R0000		1

WARRANTY INFORMATION:**N Code: I11 C Code: ZZ3**

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
W	96611 R0000	1	Low and High Pitch Horn Replacement	96611F01	0.6 M/H	96621 R0000	1

