



# Preliminary Information

## PIP5860 Diagnostic Tip: DTC P0089 P228C Set In History

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2020 - 2022	All	All	1.3 L3T	All
Chevrolet	Trailblazer	2021 - 2022	All	All	1.3 L3T	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>DTC P0089 P228C set in history when vehicle arrives at dealer</b>
<b>Cause:</b>	<b>Root cause currently being investigated by GM Engineering</b>

**Correction**

If you encounter one of these vehicles that arrive at the dealer with DTC P0089 or P228C failed in history please do not replace the high pressure fuel pump, fuel injectors or fuel rail as the root cause of the concern is being investigated through GM Engineering.

If the DTC's can be duplicated and fail as current complete the published diagnostics in Service Information for the associated code and repair as instructed.

Version History

Version	1
Modified	07/01/2022 - Created on.

