

### **Tech Tip** T-TT-0700-22

July 15, 2022

MIL ON P0AA649 / P1C8049 or Static/Distortion in AM Radio when placed in Gear

Service Category
Engine/Hybrid System

Hybrid/Battery Control System

2019-2021 RAV4 HV AWD

# **APPLICABLE VEHICLES**

2019-2021 RAV4 HV

# **CONDITION**

MIL on P0AA649 / P1C8049 or Static/Distortion in AM radio when placed in gear.

#### **RECOMMENDATIONS**

This condition is currently under investigation. Applicable vehicles are those with one or both DTC's listed and / or static or distortion heard while listening to AM Radio stations when in gears other than Park (P). Please confirm the condition of the Y6 Rear MGR cable connector and the presence of debris and / or corrosion within the connector. If the vehicle meets these conditions, please inspect the inside of the Y6 connector for the conditions listed in this Tech Tip. Please create a TAS Case and contact TAS for further instructions prior to diagnosis or repair. Take photos of all areas as directed by TAS and attach them to the TAS Case for further review.

If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts/ or details and contact TAS on the next available workday.

# **LINK REFERENCES**

This Tech Tip does not contain any link references

Expires on 01/15/2023