

WMM8 Workshop Campaign - Enabling functions on media interface

WMM8 Workshop Campaign - Enabling functions on media interface

ID Number	WMM8
Models	Macan Base/S/GTS
Model Years	2022
VIN list	Attached
Number of Affected VINs	90
Issue Description	Due to a lack of function enabling in the backend, there is a possibility that media playback from the USB stick and iPod as well as Apple Car Play via the USB interface in the center console will not work on the affected vehicles.
What Dealers should do	To make the function available in the vehicle, function enabling must be performed afterwards using the PIWIS Tester. Please carry out this repair as soon as possible on affected vehicles. The repair is now available.
TI Number	No. 170-21

Required software

PIWIS Tester 3 test software version	40.550.050 (or higher)
--------------------------------------	------------------------

Warranty processing

Validity:

This workshop campaign will be carried out up to 10/28/2026 and will be closed on that date. Please note that warranty claims can only be processed before this date.

Scope 1:

- Performing function enabling using the PIWIS Tester.
- Valid for invoicing if function enabling was performed during the sales check.

WMM8 Workshop Campaign - Enabling functions on media interface

Damage code	WMM8 66 000
Repair code	1
Working time	21 TU

Scope 2:

- Performing function enabling using the PIWIS Tester.
- Valid for invoicing if function enabling was not carried out during the sales check because this had already been carried out beforehand, for example.

Damage code	WMM8 66 000
Repair code	1
Working time	33 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.