

# WNA1 Workshop campaign - reprogramming DME control unit

---

## WNA1 Workshop campaign - reprogramming DME control unit

ID Number	WNA1
Models	911 Speedster (991) 911 GT3 RS (991)
Model Year	2019
VIN List	Attached
Number of affected VINs	605
Issue Description	<p>Internal tests have shown that the functionality of the oxygen sensor will not be consistently met over time, particularly at higher mileages or due to high thermal loads during track use.</p> <p>Under certain conditions, this can cause an error message "Engine control fault" to be displayed in the instrument cluster and the Check Engine light will be activated.</p>
What Dealers should do	<p>The DME control unit on the affected vehicles must be re-programmed with an updated data record. <b>As of the time of this posting, the repair is immediately available.</b></p>
TI Number	<a href="#">No. 4-22</a>