WNB5 Workshop campaign - Recode front passenger side door control unit

WNB5 Workshop campaign - Recode front passenger side door control unit

ID Number WNB5

Models Cayenne (9YA/9YB)

Panamera (971)

Model Years 2020-2022 VIN list Attached

Number of Affected VINs 389

Issue Description

Due to an internal fault in the door control unit on the

passenger's side (front door) the control unit is kept in

standby mode.

Due to this, there can be an increased closed-circuit current load and the 12 V vehicle electrical system battery will become discharged while the vehicle is

parked.

For this reason, the door control unit on the

passenger's side on the affected vehicles must be re-

coded with a corrected data record.

What Dealers should do The door control unit on the passenger's side on the

affected vehicles must be re-coded with a corrected

data record.

As of the time of this posting, the repair is imme-

diately available.

Please arrange for affected vehicles to be reme-

died as soon as possible.

The TI is available in PCSS and the AfterSales Docu-

ment Database.

TI Number No. 38-22

Required software

PIWIS Tester 3 test software version

40.800.020 (or higher)