

# WNF7 Workshop Campaign - Replace bolted connection of universal joint for steering column

---

## WNF7 Workshop Campaign - Replace bolted connection of universal joint for steering column

ID Number	WNF7
Models	Taycan (Y1A)
Model Years	2020-2021
VIN List	Attached
Number of affected VINs	27
Issue Description	<p>There is a possibility that the threaded joint of the universal joint for the steering column might not comply with the specifications on the affected vehicles.</p> <p>As a result, the customer may hear noise and play in the steering.</p>
What Dealers should do	<p>The screw connection on the universal joint of the steering column must be replaced on the affected vehicles.</p> <p><b>As of the time of this posting, the repair is immediately available. Parts can be ordered via PPL with no PRMS ticket needed.</b></p>
TI Number	<a href="#">No. 99-22</a>

## Parts required

Part number	Designation	Quantity/vehicle	Parts return*
WHT004955A	Internal hexagon round cheese head bolt	1 piece	No

\*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

## Warranty processing

**Validity:**

This workshop campaign will be carried out up to June 2nd, 2027 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

**Scope 1:**

Damage Code	WNF7 66 000
Repair Code	2
Labor time	42 TU

Please enter the campaign in the Warranty and Maintenance booklet for the vehicle.