

# WND5 Workshop campaign - Affixing logo on door entry guards

---

## WND5 Workshop campaign - Affixing logo on door entry guards

ID Number	WND5
Models	Taycan (Y1A/Y1C)
Model Years	2022
VIN List	Attached
Number of affected VINs	54
Issue Description	Due to an allocation error in the parts list, the GTS logo was not affixed to the door entry guards on the affected vehicles during the production process.
What dealers should do	The GTS logo must be affixed to the door entry guards on the affected vehicles. <b>As of the time of this posting, the repair is immediately available.</b> <b>Parts can be ordered via PPL with no PRMS ticket needed.</b> <b>The TI is available in PCSS and the AfterSales Document Database.</b>
TI Number	<a href="#">No. 70-22</a>

## Parts required

Part number	Designation	Quantity/vehicle	Parts return
V04015800AS	decorative film	2 ea.	No

## Warranty processing

Validity:

This workshop campaign will be carried out up to June 2nd, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

WND5 Workshop campaign - Affixing logo on door entry guards

Damage Code	WND5 66 000
Repair Code	1
Labor time	46 TU

Please enter the campaign in the Guarantee and Maintenance booklet for the vehicle.