

Subject: Engineering Information - Loss of Propulsion/Traction and Grinding Type Noise Heard After Loss of Traction and Vehicle Towed Due to Half Shaft Disconnection

This PI has been revised to end the need for information from the field. Please discard PIE0694A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2022	2022	—	—	—	—
Cadillac	XT5						
	XT6						
Chevrolet	Blazer						
	Traverse						
GMC	Acadia						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released April 22, 2022 Revised June 09, 2022 – Revised to update the Subject and Condition. Revised August 03, 2022 – Ended the need for further information from the field.