

**Subject: Engineering Information - (for Pictures Only) - Water Intrusion at Front Door Harness Connector X500 and/or X600 Resulting in Door Locks to be Inoperative, DTCs B3125, B3130 and/or B3135 Set**

*This PI has been revised to end the need for information from the field. Please discard PIE0696.*

| Brand:    | Model:   | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|----------|-------------|------|------|----|---------|---------------|
|           |          | from        | to   | from | to |         |               |
| Buick     | Enclave  | 2021        | 2022 | —    | —  | —       | —             |
| Chevrolet | Traverse |             |      |      |    |         |               |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

|                 |   |
|-----------------|---|
| <b>Version</b>  | 2   |
| <b>Modified</b> | Released April 29, 2022<br>Revised August 03, 2022 – Ended the need for further information from the field. |