



SIB 61 03 22

2022-06-14

SERVICE ACTION: CHECK WIRING HARNESS CONNECTORS

Informational Bulletin ONLY. Repair procedure to be available in July 2022.

MODEL

Model	Model Description	Production Date
K50	R 1250 GS	Apr. 21 – May 23, 2022
K51	R 1250 GS Adventure	Apr. 29 – May 23, 2022

The affected vehicles have been marked with campaign number **STOP610011** in AIR.

In order to determine if a specific vehicle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair once the procedure is available or take no further action if the motorcycle is not flagged. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

Certain motorcycles may have wiring harnesses with damaged connector pins.

Damaged connector pins can lead to electrical faults.

This bulletin will be amended with the solution, once it is available.

Motorcycles affected by this Service Actions cannot be sold until a solution is available and implemented.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 61 03 22 Checking wiring harness connectors.pdf](#)

Service Information Bulletin

General Electrical Systems

June 14, 2022

61 03 22

SERVICE ACTION: CHECK WIRING HARNESS CONNECTORS



**BMW
MOTORRAD**

Informational Bulletin ONLY. Repair procedure to be available in July 2022.

MODEL

Model	Model Description	Production Date
K50	R 1250 GS	Apr. 21 – May 23, 2022
K51	R 1250 GS Adventure	Apr. 29 – May 23, 2022

The affected vehicles have been marked with campaign number **STOP610011** in AIR.

In order to determine if a specific vehicle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair once the procedure is available or take no further action if the motorcycle is not flagged. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

Certain motorcycles may have wiring harnesses with damaged connector pins.

Damaged connector pins can lead to electrical faults.

This bulletin will be amended with the solution, once it is available.

Motorcycles affected by this Service Actions cannot be sold until a solution is available and implemented.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department