

Technical Service Bulletin

Title 55 gesture-controlled rear lid not working, B13034A

55 22 71 2067818/1 August 18, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 allroad, A4,			
S4, A5, A5			
Sportback, A5			
Cabriolet, S5, S5			
Sportback, S5			
Cabriolet, RS5, RS	2023	All	Not Applicable
5 Sportback, A6,			
S6, RS 6 Avant,			
A7, S7, RS 7, A8			
e-tron GT, and			
RS e-tron GT			

Condition

Customer states:

The gesture-controlled rear lid is not working.

Workshop findings:

The following DTC may be stored:

- B13034A: Control module for rear lid opening, incorrect component installed in the Comfort System Central Control Module (address word 0046).
- Some early MY23 vehicles may have some components of the system installed (e.g. control unit or sensor).

Page 1 of 3

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Technical Background

This function has been discontinued from Model Year 2023 for this model.

Production Solution

Not applicable.

Service

- In regards to this model, as of model year 2023 the gesture-controlled rear lid function is no longer available.
- Any related event memory entries which have been logged (refer to workshop findings) should be ignored.
- This feature cannot be enabled even if some of the parts of the system were installed at the factory.
- No work is required.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2067812) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any

Page 2 of 3

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.