
**SSM 51044 2021 Mustang Mach-E - Frunk System Fault Service
Required Message After BCM Software Update - Built On Or Before
06-Jul-2021**

Some 2021 Mustang Mach-E vehicles built on or before 6-Jul-2021 may exhibit a warning message in the instrument panel cluster (IPC) which states Frunk System Fault Service Required after the body control module (BCM) software update or programmable module installation (PMI) application have been run with the Ford Diagnosis and Repair System (FDRS). To correct this condition, download and run the FDRS the generic function module (GFM) software update application.