



# Campaign Tip

|                            |  |                   |                          |
|----------------------------|--|-------------------|--------------------------|
| <b>This notice is for:</b> | ✓ Dealer Principal   | ✓ Service Manager | ✓ Warranty Administrator |
|                            | ✓ Sales Manager  | ✓ Parts Manager   | ✓ Technicians            |
| <b>Date</b>                | August 22, 2022  |                   |                          |
| <b>Topic</b>               | Minimum battery charger requirements during software updates |                   |                          |



The ELSA Repair Manual and TSB 01-18-12 - Software Version Management (2014603/18) have been recently updated with a new minimum battery charging amperage.

A Battery Tester/Charger capable of **minimum 70 Amp** continuous supply must also be used for all campaign software updates.

If your dealership does not have a battery charger that meets these requirements, please obtain one as soon as possible.

*NOTE: VAS5908 -Volkswagen MRT- exceeds the 70A minimum spec.  
(See VSE-22-14 on ServiceNet for information on the VAS5908 MRT Auto-  
Shipment AT-464)*

<END OF MESSAGE>