

TECHNICAL SERVICE BULLETIN

Classification:	Reference:	Date:		
HA22-003A	NTB22-023A	July 12, 2022		

BLOWER MOTOR MAKES CLICKING NOISE DUE TO SNOW INTRUSION

This bulletin has been amended. See AMENDMENT HISTORY on the last page.

Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2021 Rogue (T33)

APPLIED ENGINES: PR25DD

IF YOU CONFIRM

A clicking noise is heard coming from the HVAC case while the blower is operating,

AND

Snow and/or ice is found in the HVAC blower motor case.

ACTION

Replace the cowl top cover with one in the **PARTS INFORMATION**.

 Refer to the ESM: BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > EXTERIOR > REMOVAL AND INSTALLATION > COWL TOP > Removal and Installation




Figure 1

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire ESM service procedure as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

GRADE	DESCRIPTION	SCRIPTION PART NUMBER	
S, SV	Cowl Top Cover	66862-6RR0B	1
SL, Platinum	Cowl Top Cover	66862-6RR2B	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Install Cowl Top Cover	(1)	UE24AA	ZL	32	(2)

- (1) Reference the **PARTS INFORMATION** above and use the Cowl Top Cover as the Primary Failed Part (PFP).
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 22, 2022	NTB22-023	Original bulletin published
July 12, 2022	NTB22-023A	PARTS INFORMATION updated

2/2 NTB22-023A